



**AIRMARK OVERHAUL, INC.**  
6001 N.W. 29th Avenue, Ft. Lauderdale, FL 33309  
(954) 970-3200 / (800) 282-3202 / Fax (954) 970-3400

MODEL: TSIO-360-FB

**ENGINE OVERHAUL QUOTE**

DATE: 3/1/2021

OVERHAUL/EXCHANGE PRICE: \$39,400.00

\*\*\* VALID FOR 30 DAYS \*\*\*

\*\* Overhaul to Factory New Fits and Clearances \*\*

\*\*Roller Tappet configurations have additional costs\*\*

TYPE OF CYLINDER: FACTORY NEW CONTINENTAL

LEAD TIME: 5 WEEKS

QUOTED TO: KONSTANTIN KRISHTOP

ATTN:

COMMENTS:

ADDRESS:

CITY:

EMAIL: krishtopks@gmail.com

STATE:

ZIP:

PHONE:

FAX:

**Includes the following accessories that are checked. If additional, costs will be shown in box.**

☒ MAGNETOS:

☒ MAGNETOS HARNESS:

☒ STARTER ADAPTER:

☒ TURBOCHARGER:

☐ HOSE KIT:

☐ VACUUM PUMP:

☐

☒ SPARK PLUGS:

☐ CARBURETOR:

☒ OIL COOLER:

☐ WASTEGATE:

☐ LORD MOUNTS:

☐ GOVERNORS:

☐

☒ STARTER:

☐ ALTERNATOR (W/O DRIVE):

☒ FUEL INJECTION SYSTEM:

☐ CONTROLLER:

☐ CONTROLLER2:

☐ RELIEF VALVE:

☐

**Standard Features with an Airmark Engine Overhaul**

\* Crankshaft is dynamically balanced to less than .25 inch ounces to eliminate rotational imbalance and excess vibration (100% improvement over OEM tolerance standard)

\* Connecting rods are balanced for total weight and equal mass distribution

\* Cylinder valves and seats are precision ground to maximize cylinder performance

\* Hydraulic lifter bleed down rates matched

\* Ultra-Sonic Inspection of the crankshaft for subsurface flaws (TCM only)

\* All Airworthiness Directives and Mandatory Service Bulletins are complied with

\* Manufacturers required 100% parts replacement (OUR minimum standard)

\* All parts are cleaned by chemical and/or mechanical means

\* Detailed inspection of all parts: Visual and Dimensional

\* Steel parts are Magnetic Particle Inspected

\* Non-Ferrous parts are Liquid Penetrant Inspected

\* Alodine corrosion treatment on most aluminum parts

\* Painted with a custom high temperature enamel finish

\* Complete traceability of all parts installed

\* Fully tested in our diagnostically equipped test cell

Warranted for 1 year or 480 hours at 100% and a limited pro-rated warranty will continue to 2 years or TBO, whichever occurs first from the date of overhaul. Accessories are 6 months or 240 hours

Core Deposit: \$17,500.00

Quoted by: DAVID WILLIAMS

Overhaul price is contingent upon your engine core crankcase & crankshaft being repairable  
Engine must be a complete and normal core.

All pricing is subject to change without notice. Core charges may apply. Freight is additional.

We invite you to visit our website at: [www.airmarkoverhaul.com](http://www.airmarkoverhaul.com)

Quote #: 18492